







QTY数量	DESCRIBE描述	SUPPLIER供应部门	REFERENCE参考信息	MATERIAL材料	FINISH颜色	PROCESSES工艺	UNIT WEIGHT单件重量 (Kg)	TOTAL WEIGHT总重量 (Kg)
	8M90030200	SUPPLIER	REFERENCE			cut/weld/drill/polish/paint	100.18	




镜子

局部视图 AH
比例 1:2

此处按实际拉槽装排铰

技术要求(Technical Requirements):

- 1、供货方须相应配同色的连接器, 螺杆菌连接器要装在相应位置, 以防止孔位偏差;
(The supplier needs to provide the connector and match the color;
The threaded rod must be pre-installed into the correct location to avoid the deviation)
- 2、金属件要求无拔锋, 焊接牢固, 无虚焊, 承重部位必须清焊;
(The metal parts must be smoothly, strong welding, full weld on the loading location)
(金属件所有有光孔部位不允许有影响外观效果的焊疤;
Forbidden the welding mark on the appearance surface of metal parts)
- 3、注意公差配合: 螺杆菌和玻璃罩孔与螺杆菌配合时挂扣的入口, 如未注明公差按负公差0.5mm加工。
(Take note the tolerance for mirror, glass, the hook which needs to be assembled with bar and so on, the unspecified tolerance is -0.5mm.)
- 5、所有可见螺丝均为内六角螺丝
(All the appearance screws must be allen screws)
- 6、所有螺柱、玻璃、大理石边沿和4角都要磨边, 金属件所有边角无拔锋(无毛刺, 防止伤人。
(All mirrors, glass, marble 4 sides and 4 angles need to sanding, all corners of metal furniture need to polish, no burr, prevent injuries.)
- 7、凡是涉及到走线的产品, 供货方必须穿好电线。
The supplier must wear all wire.
- 8、供货方必须装配好由供货方生产的配件产品, 例如层板托、连接器。
(the supplier must Pre assembled accessory, such as lamination, connector.)

SHEET FORMAT 图纸大小		A3		UNITS单位		mm		8M90030200		-总装		PROJECT NO.内部单号		STORE CODE店铺号	
DRAWN BY制图		FrazerZhu		SCALE比例		1:20						ORDER NO.订单号			
ORDER DATE下单日期		00/00/00		DELIVERY DATE入库日期		00/00/00		----							
CLIENT DRAWING图户图		Proy V.0		VERSION版本				----							
ASSEMBLED IN:组装场所		INTERIOR		DRAWING TYPE图纸类型		MANUFACTURING		----							