

DESCRIBE描述	ZARA CODE	MATERIAL材料	FINISH颜色	PROCESSES工艺	UNIT WEIGHT单件重量(Kg)
8Z70472800		AL 铝	3962-WD-02A	cut/weld/drill/polish/paint	363.23

150

1200

1200

1200

1200

1200

1200

150

2200

2265

2265

C1

C2

C2

C2

C2

C2

C2

C3

C4

C5

C5

C5

C5

C5

C5

C4

C4

C5

C5

C5

C5

C5

C5

C4

2060

2060

2060

923.5

1200

1200

1200

1200

1200

250

B1

B2

B2

B2

B2

B3

B1

B2

B2

B2

B2

B3

B1

B2

B2

B2

B2

B3

以过道门套中线对齐
往两边并排安装

①

②

No. 序号	Part Description 零件描述	Quantity 数量	Material 材质	Finish 颜色
1	5Z71472801	1	AL 铝	3962店-WD-02A
2	5Z71472802	1	AL 铝	3962店-WD-02A

L2楼层热转印天花

序号	长度L	宽度W	高 H	数量
B1	2060	923.5	一长边折16mm, 两短一长边折10mm	3PCS
B2	2060	1200	四边折10mm	12PCS
B3	2060	250	四边折10mm	3PCS
C1	2200	150	一长一短边折16mm, 一长一短边折10mm	1PCS
C2	2200	1200	一短边折16mm, 两长一短边折10mm	6PCS
C3	2200	150	一长一短边折16mm, 一长一短边折10mm	1PCS
C4	2265	150	一长边折16mm, 两短一长边折10mm	4PCS
C5	2265	1200	四边折10mm	12PCS

SHEET FORMAT 图纸大小	A3	UNITS单位	mm	8Z70472800	-总装	PROJECT NO.内部单号	STORE CODE店铺号
DRAWN BY制图	FrazerZhu	SCALE比例	1:80			0000/00	0000
ORDER DATE下单日期	00/00/00	DELIVERY DATE入库日期	00/00/00			ORDER NO.订单号	
CLIENT DRAWING客户图	Proy V.0	VERSION版本	V.0			000	
ASSEMBLED IN:组装场所	INTERIOR	DRAWING TYPE图纸类型	MANUFACTURING	3962-WD-02A L2-hot print ceiling		ZARA CAAMAÑOASIA®	

根据现场安装情况
进行裁剪

技术要求(Technical Requirements):
1、供货方要相应配同色的连接件; 螺杆类连接件要装在相应位置, 以防止孔位偏差;
(The supplier needs to provide the connectorand match the color;
The threaded rod must be pre-install into the correct location to avoid the deviation)
2、金属件要求无拔锋, 焊接牢固, 无虚焊, 承重部位必须满焊;
(The metal parts must be smoothly, strong welding, full weld on the loading location)
3、金属件所有见光部位不允许有影响外观效果的焊疤;
(Forbid the welding mark on the appearance surface of metal parts)
4、注意公差配合: 镜子和玻璃尺寸, 需与挂臂配合的挂钩内卡口, 如未注明公差按负公差0.5mm加工.
(Take note the tolerance for mirror,glass, the hook which needs to assembled with bar and so on, the unspecified tolerance is -0.5mm.)
5、所有可见螺丝均为内六角螺丝.
(All the appearance screws must be allen screws)
6、所有镜子、玻璃、大理石4边和4角都要磨边, 金属件所有边角无拔锋\无毛刺, 防止伤人。
(All mirrors, glass, marble 4 sides and 4 angles need to sanding, all corners of metal furniture need to polish,no burr, prevent injuries.)
7、凡是涉及到走线的产品, 供货方必须穿好电线。
(The supplier must wear all wire.)
8、供货方必须装配好由供货方生产的配套产品, 例如层板托、连接件。
(the supplier must Pre assembled accessory, such as lamination, connector.)
9 所有部件焊接时要磨45°左右的斜边,辅助焊接,超过轮廓线外的焊点要磨平。