










MACHINE



节点
DETAIL

BC-L1-07		QTY.
L1	2700x490xH2050	x1
		-





DESCRIBE描述	ZARA CODE	MATERIAL材料	FINISH颜色	PROCESSES工艺	UNIT WEIGHT单件重量(Kg)
8Z80129400	BC-L1-07-3962FO	IRON铁/防火MDF	3962-BLACK STEEL/3962-WD-12_拼接面黑色底漆	cut/weld/drill/polish/paint	685.55

技术要求(Technical Requirements):

- 供货方要相应配同色的连接件; 螺杆类连接件要装在相应位置, 以防止孔位偏差;
(The supplier needs to provide the connector and match the color;
The threaded rod must be pre-install into the correct location to avoid the deviation)
- 金属件要求无接缝, 焊接牢固, 无虚焊, 承重部位必须满焊;
(The metal parts must be smoothly, strong welding, full weld on the loading location)
- 金属件所有见光部位不允许有影响外观效果的焊疤;
(Forbid the welding mark on the appearance surface of metal parts)
- 注意公差配合: 镜子和玻璃尺寸, 需与挂臂配合的挂钩内卡口, 如未注明公差按负公差0.5mm加工.
(Take note the tolerance for mirror, glass, the hook which needs to assembled with bar and so on, the unspecified tolerance is -0.5mm.)
- 所有可见螺丝均为内六角螺丝.
(All the appearance screws must be allen screws)
- 所有镜子、玻璃、大理石4边和4角都要磨边, 金属件所有边角无坡锋\无毛刺, 防止伤人.
(All mirrors, glass, marble 4 sides and 4 angles need to sanding, all corners of metal furniture need to polish, no burr, prevent injuries.)
- 凡是涉及到走线的产品, 供货方必须穿好电线.
(The supplier must wear all wire.)
- 供货方必须装配好由供货方生产的配套产品, 例如层板托、连接件.
(the supplier must Pre assembled accessory, such as lamination, connector.)
- 所有部件焊接时要磨45°左右的斜边, 辅助焊接, 超过轮廓线外的焊点要磨平。

局部视图 D
比例 1:2

DESCRIBE描述	ZARA CODE	MATERIAL材料	FINISH颜色	PROCESSES工艺			UNIT WEIGHT单件重量 (Kg)	
8Z80129400	BC-L1-07-3962FO	IRON铁/防火MDF	3962-BLACK STEEL/3962-WD-12_拼接面黑色底漆	cut/weld/drill/polish/paint			685.55	

No. 序号	Part Description 零件描述	Quantity 数量	Material 材质	Finish 颜色
1	5Z82129401	1	防火MDF	3962-WD-12/拼接面_黑色底漆
2	5Z82129402	3	防火MDF	3962-WD-12
3	5Z82129403	3	防火MDF	3962-WD-12
4	5Z82129404	4	防火MDF	3962-WD-12
5	5Z81129405	4	IRON铁	3962-BLACK STEEL

走线到底

Paint Area: 40m²

Paint Color: 3962-WD-12

Paint Area: 1.5m²

Paint Color: Black Primer

黑色底漆

技术要求(Technical Requirements):

1、供货方要相应配同色的连接件; 螺杆类连接件要装在相应位置, 以防止孔位偏差;

(The supplier needs to provide the connector and match the color;

The threaded rod must be pre-install into the correct location to avoid the deviation)

2、金属件要求无拔锋, 焊接牢固, 无虚焊, 承重部位必须满焊;

(The metal parts must be smoothly, strong welding, full weld on the loading location)

3、金属件所有见光部位不允许有影响外观效果的焊疤;

(Forbid the welding mark on the appearance surface of metal parts)

4、注意公差配合: 镜子和玻璃尺寸, 需与挂臂配合的挂钩内卡口, 如未注明公差按负公差0.5mm加工.

(Take note the tolerance for mirror, glass, the hook which needs to assembled with bar and so on, the unspecified tolerance is -0.5mm.)

5、所有可见螺丝均为内六角螺丝.

(All the appearance screws must be allen screws)

6、所有镜子、玻璃、大理石4边和4角都要磨边, 金属件所有边角无坡锋\无毛刺, 防止伤人.

(All mirrors, glass, marble 4 sides and 4 angles need to sanding, all corners of metal furniture need to polish, no burr, prevent injuries.)

7、凡是涉及到走线的产品, 供货方必须穿好电线.

(The supplier must wear all wire.)

8、供货方必须装配好由供货方生产的配套产品, 例如层板托、连接件.

(the supplier must Pre assembled accessory, such as lamination, connector.)

9.所有部件焊接时要磨45°左右的斜边, 辅助焊接, 超过轮廓线外的焊点要磨平。

SHEET FORMAT 图纸大小	A3	UNITS 单位	mm	8Z80129400	-BOM	PROJECT NO. 内部单号	STORE CODE 店铺号
DRAWN BY 制图	FrazerZhu	SCALE 比例	1:20			0000/00	0000
ORDER DATE 下单日期	00/00/00	DELIVERY DATE 入库日期	00/00/00			ORDER NO. 订单号	
CLIENT DRAWING 客户图	Proy V.0	VERSION 版本	V.0			000	
ASSEMBLED IN: 组装场所	INTERIOR	DRAWING TYPE 图纸类型	MANUFACTURING	CABINET L2700XD490XH205		ZARA	
						CAAMAÑOASIA®	
创建日期(Created Date)		上次保存的日期(Last Saved Date)					
2026年9月18日 14:02:18		2026年9月18日 14:54:33					
Path存储路径:E:\Frazer Zhu NEW\ZARA 项目\ZARA 3962 OM\8Z80129400 BC-L1-07\8Z80129400							
				共 2 张 第 2 张			