







DESCRIBE描述	MD CODE	MATERIAL材料	FINISH颜色	PROCESSES工艺	UNIT WEIGHT单件重量(Kg)
8M90054300		IRON铁/防火MDF	NEGRO LATONADO/RAL 9004哑光/双贴ROBLE TEÑIDO FRESNO	cut/weld/drill/polish/paint	117.25



技术要求(Technical Requirements):

- 1、供货方要相应配同色的连接器, 螺柱类连接器要装在相应位置, 以防止孔位偏差;
(The supplier needs to provide the connector and match the color;
The threaded rod must be pre-install into the correct location to avoid the deviation)
- 2、金属件要求无坡锋, 焊接牢固, 无虚焊, 承重部位必须满焊;
(The metal parts must be smoothly, strong welding, full weld on the loading location)
- 3、金属件所有可见光部位不允许有影响外观效果的焊疤;
(Forbid the welding mark on the appearance surface of metal parts)
- 4、注意公差配合: 螺柱和玻璃尺寸, 需与指定配合的挂钩内卡口, 如未注明公差按负公差0.5mm加工。
(Take note the tolerance for mirror, glass, the hook which needs to assembled with bar and so on, the unspecified tolerance is -0.5mm.)
- 5、所有可见螺丝均为内六角螺丝
(All the appearance screws must be allen screws)
- 6、所有棱、玻璃、大理石4边和4角都要磨边, 金属件所有边角无坡锋/无毛刺, 防止伤人。
(All mirrors, glass, marble 4 edges and 4 angles need to sanding, all corners of metal furniture need to polish no burr, prevent injuries)
- 7、凡触及到走线的产品, 供货方必须穿好电线。
(The supplier must wear all wire.)
- 8、供货方必须装配好由供货方生产的配套零件, 例如层板托、连接器。
(The supplier must Pre assembled accessory, such as lamination, connector.)
- 9、所有部件都要磨边45°左右的斜边, 辅助磨边, 超过轮廓线外的焊点都要磨平。

SHEET FORMAT 图纸大小		UNITS单位 mm	8M90054300	-总装	PROJECT NO.内部单号 0000/00	STORE CODE店铺号 0000
DRAWN BY制图 FrazerZhu		SCALE比例 1:12			ORDER NO.订单号 000	
ORDER DATE下单日期 00/00/00		DELIVERY DATE入库日期 00/00/00	MOSTRADOR CAJA CARRITO PERCHAS 100 MIDDLE ROBLE FRESNO			
CLIENT DRAWING图户图 Proy V.0		VERSION版本 V.0				
ASSEMBLED IN:组装场所 INTERIOR		DRAWING TYPE图纸类型 MANUFACTURING				

